

Inspection Photos
Location Name: Walker 12-4
Location ID: 313147



Photo 1. Overview of location taken facing north. Wellhead sign knocked over.



Photo 2. Access road overgrown.

