

**Inspection Photos**  
**Operator: BP America**  
**API: 067-07754**  
**Date: 9/15/2020**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the southeastern corner facing northward. Revegetation is progressing within the interim reclamation area, largely with grasses such as western wheatgrass and sand dropseed.



Photo 3. View of reference area vegetation comprised of ponderosa pine woodland with understory of gambel oak, snowberry, black sage, and western wheatgrass.



Photos 4/5. Locked gate coming in (left) and leaving (right).