

Inspection Photos

9/17/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 423444

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 423444



Photo 1: Photo taken from the northeast end of the Location, facing south. Photo provides overview of the Location.



Photo 2: Photo taken from the northeast end of the Location, facing west. Photo provides overview of the Location

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 423444



Photo 3: Photo taken from one of the stormwater ditches on the Location, facing southwest. Stormwater channelization and cutting within the ditch is becoming evident and Operator is advised to implement BMPs in conjunction with the ditches to alleviate stormwater velocity within the ditch, to mitigate further incising within the ditch.



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 423444



Photo 5: Photo shows sediment trap and culvert on the north end of the Location



Photo 6: Photo shows example of Musk thistle weeds observed on the Location that appear to have reached seed head maturity and dispersal

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 423444



Photo 7: Photo taken from the west end of the Location. Photo shows example of Houndstongue rosettes observed on the Location



Photo 8: Photo taken from the south end of the Location. Photo shows example of Musk thistle weeds observed on the Location that appear to have reached seed head maturity and dispersal

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 423444



Photo 9: Photo of taken from the south end of the Locaiton, facing North. Photo provides an overview of the Location.



Photo 10: Photo taken from the north end of the Location. Photo shows cable debris remaining.