

Final Reclamation Inspection

September 15, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 305170

Inspection Document #: 697502003

Weld County, CO

SWSE Section 5 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BECKER #6
Location ID: 305170



Photo 1. Photo taken from the well location, facing South. Photo illustrates the Operator has plugged the well and final reclamation activities have been initiated by removing gravel and performing compaction alleviation.

Note: Portions of the new Noble D05-10 pad overlap with the former well location access road and flowline area.

Inspection Photos
Location Name: BECKER #6
Location ID: 305170



Photo 2. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates the Operator has decommissioned the tank battery. Equipment, meter house, still remains at the location. In addition, final reclamation activities have been initiated by removing gravel and performing compaction alleviation.

Inspection Photos
Location Name: BECKER #6
Location ID: 305170



Photo 3. Photo taken from the associated offsite tank battery location, facing Northwest. See comments under Photo 2.