

Final Reclamation Inspection

September 15, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 306543

Inspection Document #: 697502007

Weld County, CO

SWNE Section 5 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BECKER #6-11I
Location ID: 306543



Photo 1. Photo taken from the associated offsite tank battery location, facing West. Photo illustrates Operator has decommissioned the tank battery; however, there is still equipment, riser, that needs to be removed.

Inspection Photos
Location Name: BECKER #6-11I
Location ID: 306543



Photo 2. Photo taken from the associated offsite tank battery location, facing West. See comments under Photo 1.