

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 1. Overview of location taken facing southeast.



Photo 2. Overview of location taken facing south.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 3. Debris and/or equipment stored on location.



Photo 4. Debris and/or equipment stored on location.

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



**Photo 5. Debris and/or equipment stored on location.
Evidence of movement during recent wind event.**



Photo 6. Debris and/or equipment stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 7. Debris and/or equipment stored on location.



Photo 8. Debris and/or equipment stored on location.



Inspection Photos
Location Name: Anderson 43-29
Location ID: 313194



Photo 9. Debris and/or equipment stored on location.



Photo 10. No wellhead sign.

