

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 1. Overview of location taken facing south.



Photo 2. Overview of location taken facing southwest.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 3. Wellhead sign knocked over. Hissing at wellhead.



Photo 4. Unmarked risers.

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 5. Incomplete or missing tank labels.



Photo 6. Incomplete or missing tank labels.



Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 7. Erosion from location down to access road. Photo on access road looking towards location.



Photo 8. Erosion from location down to access road. Photo taken on location.

Inspection Photos
Location Name: Bighole-Fed Land Bank 13-1
Location ID: 312931



Photo 9. Erosion from location down to access road. Photo on location looking towards access road.



Photo 10. Sediment migration off access road.