

Inspection Photos

Location Name: ROUSE USX AB-67N64W /33SWSW

Location #: 302629



Colorado Oil & Gas Conservation Commission
40.52384, -104.56254, 4778.0ft, 154°
09/16/2020 11:59:28

Photo #1

Rouse USX AB 33-13 (05-123-29500) Wellsite
Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.52257, -104.56409, 4774.8ft, 324°
09/16/2020 13:47:05

Photo #2

Rouse USX AB 33-13, 33-11, 33-14, 33-25,
Rouse USX A 05-01, 05-02, 05-07, 05-08, 5-17
Battery site
Inactive | Shut-down