

Inspection Photos
Location Name: ROUSE USX A-66N64W /5SENE
Location #: 302582



Photo #1

Rouse USX A 05-08 (05-123-29423) Wellsite

Shut-In | SI

Weeds



Photo #2

**Rouse USX AB 33-13, 33-11, 33-14, 33-25,
Rouse USX A 05-01, 05-02, 05-07, 05-08, 5-17**

Battery site

Inactive | Shut-down