

Inspection Photos

API: 071-06895

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06895 | Date: 9/16/2020

Inspection Photos



Photo 1. Facing north toward the access road which has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06895 | Date: 9/16/2020

Inspection Photos



Photo 2. Facing northwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06895 | Date: 9/16/2020

Inspection Photos



Photo 3. Facing northeast along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06895 | Date: 9/16/2020

Inspection Photos



Photo 4. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06895 | Date: 9/16/2020

Inspection Photos



Photo 5. Facing south toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06895 | Date: 9/16/2020

Inspection Photos



Photo 6. Facing south at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06895 | Date: 9/16/2020