

Inspection Photos

API: 071-06723

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 9/16/2020

Inspection Photos



Photo 1. Facing southeast toward the access road which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 9/16/2020

Inspection Photos



Photo 2. The access road remains to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 9/16/2020

Inspection Photos



Photo 3. Facing southeast toward the location which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 9/16/2020

Inspection Photos



Photo 4. It appears there was recent work performed at the south side of the location with rock rip/rap installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 9/16/2020

Inspection Photos



Photo 5. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 9/16/2020

Inspection Photos



Photo 6. Facing east toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 9/16/2020

Inspection Photos



Photo 7. Facing west toward the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06723 | Date: 9/16/2020