

Inspection Photos

API: 071-07630

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07630 | Date: 9/16/2020

Inspection Photos



Photo 1. Facing northeast toward the access road which has not been recontoured and reclaimed..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07630 | Date: 9/16/2020

Inspection Photos



Photo 2. The access road remains to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07630 | Date: 9/16/2020

Inspection Photos



Photo 3. Facing northeast toward the location which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07630 | Date: 9/16/2020

Inspection Photos



Photo 4. The pit remains at the northeast side of the location at the base of the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07630 | Date: 9/16/2020

Inspection Photos



Photo 5. Facing west at the location. The top of the mountain has been leveled off for the wellpad and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07630 | Date: 9/16/2020

Inspection Photos



Photo 6. Facing southwest toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07630 | Date: 9/16/2020

Inspection Photos



Photo 7. Facing southwest toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07630 | Date: 9/16/2020