

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2020

Submitted Date:

09/18/2020

Document Number:

696103745**FIELD INSPECTION FORM**Loc ID 306369 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288209	WELL	TA	11/01/2019	OW	123-24545	WEST IRRIGATION-USX AB 33-15	TA

General Comment:

This is a WELL / BATTERY inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (306369, 421229).
(Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery formerly served 1 Location ID (306368).
(Well(s): 1: Plugged & Abandoned | PA).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Propane		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		

Comment: Barbed wire.			
Corrective Action:		Date:	
Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment: Calibration card indicates NO calibration within last year. Last calibration: 02/12/2020. Meter is NOT active.			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment: Appears plumbed to surface.			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Wellhead: w/ Master & casing valves.			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment: 2: ECD scrubbers. 1: At Battery: Propane tank. Placarded.			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment: ECD #1, 2: Controls crude oil tanks VOCs. ECD #3: Controls separator VOCs. Pilots: OFF Shut-down.			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: Centralized Battery serves 2 Location IDs (306369, 421229). (Well(s): 2: Temporarily Abandoned TA). Centralized Battery formerly served 1 Location ID (306368). (Well(s): 1: Plugged & Abandoned PA).					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ crude oil tanks.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLS	STEEL AST		40.523567,-104.554179
Comment: Equalizer lines connect crude oil tanks.					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O vaults.				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 288209 Type: WELL API Number: 123-24545 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment:

Temporarily Abandoned | TA.

Well disconnected from flowline.

Blue TA tag posted at wellsite.

Locked-Out, Tagged-Out | LOTO.

COGCC records indicate last production: 10/2018.

Form 4 Sundry doc. #Form 4 Sundry doc. #402456602 indicates

Temporarily Abandoned | TA status date: 07/01/2019.

Form 21-MIT doc. #402107712 indicates MIT done: 07/02/2019. Approved.

Form 42 MIT Notice doc. #402089376 date: 07/02/2019. Approved.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 09/16/2020 at approximately 14:26 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WEST IRRIGATION-USX AB-67N64W /33SWSE Location ID: 306369 Well Name: West Irrigation-USX AB 33-15 API: 05-123-24545 Location County: Weld County, Colorado Weather: Mostly clear w/ haze, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (306369, 421229). (Well(s): 2: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 1 Location ID (306368). (Well(s): 1: Plugged & Abandoned PA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/18/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103746	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5251257