

Inspection Photos
Location Name: State 16-2
Location ID: 312919



Photo 1. Overview of location taken facing south.



Inspection Photos
Location Name: State 16-2
Location ID: 312919



Photo 2. Hissing at wellhead.



Photo 3. Evidence of sediment migration onto location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: State 16-2
Location ID: 312919



Photo 4. Evidence of sediment migration down access road.



Photo 5. Evidence of sediment migration down access road.

