

Inspection Photos

API#107-06206

Operator: North Finn

Insp#: 692402512

Insp Date: 9/16/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to East 2016



Photo#2:
Overview of Location to East 2020.

September 16, 2020



Photo#2:
Four marked anchors & sign remain on site.



Photo#3:
Four marked anchors & sign remain on site.

September 16, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Finn PA Breeze API#107-06206



Photo#4:
Overview of Location to West

September 16, 2020