

Inspection Photos

API#107-06189

Operator: North Finn

Insp#: 692402514

Insp Date: 9/16/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to West

September 16, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: North Finn PA Breeze API#107-06189



Photo#2:
View of Associated lines, risers, Debris on Location.

September 16, 2020