

Inspection Photos
Location Name: Schaal 41-31
API: 05-125-11133



1. Wellhead



2. Pictures of access to wellhead



Access has erosion and deep tracks through the pasture. Some areas are impassable in a pickup and tracks outside the main access are beginning to form.

Inspection Photos
Location Name: Schaal 41-31
API: 05-125-11133



3. Pictures of access to wellhead