

Inspection Photos

API: 071-07244

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/16/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07244 | Date: 9/16/2020

Inspection Photos



Photo 1. Facing northwest along the access road. Erosion has occurred along the road that needs to be repaired. Arrow points to 4.5 ft. shovel.

Lat/Long:37.25888,-104.68137.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07244 | Date: 9/16/2020

Inspection Photos



Photo 2. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07244 | Date: 9/16/2020

Inspection Photos



Photo 3. There is oil stained soil around the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07244 | Date: 9/16/2020