

# Inspection Photos

9/16/2020

Operator: NONSUCH NATURAL GAS INC -  
10163

Location ID: 453726  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 453726



**Photo 1:** Photo of 200 bbl condensate tank on the southern end of the Location. Photo shows secondary containment remains out of compliance with Rule 906.d.(1); Vegetation remains established within BMP compromising the imperviability of the containment; BMP insufficient to contain contents of tank and sufficient freeboard to contain precipitation.



**Photo 2:** Photo taken from the Location facing northeast. Photo shows equipment not needed for production has been removed.