

Inspection Photos

API#045-06850

Operator: Caerus

Inspection #: 692402526

Inspection Date: 9/18/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast.

September 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Mamm Creek API#045-06850



Photo#2:
Vegetation on slopes.

September 18, 2020



Photo#3:
Marked Anchor.

September 18, 2020



Photo#4:
Secondary containment covered with screen