



Photo#1:  
Overview of Location to West.

September 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus PA Knight API#045-06832



Photo#2:  
Views of access road fill slope.

September 18, 2020