

Inspection Photos
Location Name: State 2-12
Location ID: 328919



Photo 1 – Wellhead Sign



Photo 2 – Pumping Unit, Stained Soil at Wellhead

Inspection Photos
Location Name: State 2-12
Location ID: 328919



Photo 3 – Stained Soil at Gas Engine



Photo 4 – Stained Soil at Gas Engine

Inspection Photos
Location Name: State 2-12
Location ID: 328919



Photo 5 – Unused Tubing




Photo 6 – Stained Soil