

KP Kauffman - COGCC Inspection Photos
Location: H. Huett Consolidation OLF Release
Spill ID # 478005 Date 9/21/2020



View of spill response and excavation activity on the south side of WCR 8; view west.



Closer view of area of release and hydrocarbon stained soils; view west.

KP Kauffman - COGCC Inspection Photos
Location: H. Huett Consolidation OLF Release
Spill ID # 478005 Date 9/21/2020



East bellhole excavation; 6" CS H Huett Consolidation OLF exposed and cut with 3" OD DR 11 HDPE pipe being slip lined through failed section of pipe.

West bellhole excavation; 6" CS H Huett Consolidation OLF exposed and cut with 3" OD DR 11 HDPE pipe being slip lined through failed section of pipe. A 2" CS OLF is also exposed in the excavation.