

Inspection Photos
Location Name: ROUSE USX A-66N64W /5SENE
Location #: 302582



Colorado Oil & Gas Conservation Commission
40.51644, -104.56693, 4769.6ft, 29°
09/16/2020 13:16:49

Photo #1

Rouse USX A 05-08 (05-123-29423) Wellsite

Shut-In | SI

Weeds
prior insp.



Colorado Oil & Gas Conservation Commission
40.51646, -104.56692, 4775.8ft, 22°
09/21/2020 16:37:28

Photo #2

Rouse USX A 05-08 Wellsite

Shut-In | SI

Weeds: Mitigated

Inspection Photos

Location Name: ROUSE USX A-66N64W /5SENE

Location #: 302582



Colorado Oil & Gas Conservation Commission
40.52257, -104.56409, 4774.8ft, 324°
09/16/2020 13:47:05

Photo #3

**Rouse USX AB 33-13, 33-11, 33-14, 33-25,
Rouse USX A 05-01, 05-02, 05-07, 05-08, 5-17**

Battery site

Inactive | Shut-down

prior insp.