

Inspection Photos
Operator: BP America
API: 067-06904
Date: 9/18/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as smooth brome and western wheatgrass.



Photo 3. View of the reference area comprised of irrigated grass field with a mixture of grasses in a grazed (and not identifiable) condition.