

Inspection Photos
Location Name: Henderson #1
Location ID: 331730




Photo 1 – Tank Battery



Photo 2 – Pumping Unit/Wellhead



Inspection Photos
Location Name: Henderson #1
Location ID: 331730



Photo 3 – Heater Treaters, Gas Meter




Photo 4 – Stained Soil cleaned Up



Inspection Photos
Location Name: Henderson #1
Location ID: 331730



Photo 5 – Inside Heater Shed, Stained Soil cleaned up



**Photo 6 – East Heater Treater; disconnected no longer in use.
Risers marked**



Inspection Photos
Location Name: Henderson #1
Location ID: 331730



Photo 7 – Inside Engine Shed, Stained Soil



Photo 8 – Stained Soil at NE Tank

Inspection Photos
Location Name: Henderson #1
Location ID: 331730



Photo 9 – Inside Tank Berm, Stained Soil. Risers now marked




Photo 10 – Inside Tank Berm, Stained Soil. Risers now marked



Inspection Photos
Location Name: Henderson #1
Location ID: 331730



Photo 11 – Skim Tank missing NFPA Label



Photo 12 – Oil/Hydrocarbon on Pit. Stained Soil on the Edges



Inspection Photos
Location Name: Henderson #1
Location ID: 331730



Photo 11 – Oil/Hydrocarbon on Pit. Stained Soil on the Edges



Photo 12 – Oil/Hydrocarbon on Pit. Stained Soil on the Edges

Inspection Photos
Location Name: Henderson #1
Location ID: 331730




Photo 13 – Oil/Hydrocarbon on Pit. Stained Soil on the Edges