

FORM  
INSPRev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2020

Submitted Date:

09/23/2020

Document Number:

693503521

## FIELD INSPECTION FORM

Loc ID 305447 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

21 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434333	WELL	PR	01/07/2019	OW	123-38104	Woolley Sosa 2A-7H-E168	PR
434334	WELL	PR	07/26/2017	OW	123-38105	Woolley Becky 2F-7H-E168	PR
434335	WELL	PR	01/07/2019	OW	123-38106	Woolley Sosa 2D-7H-E168	PR
434336	WELL	PR	01/07/2019	OW	123-38107	Woolley Becky 2D-7H-E168	PR
434337	WELL	PR	01/07/2019	OW	123-38108	Woolley Sosa 2B-7H-E168	PR
434338	WELL	PR	01/07/2019	OW	123-38109	Woolley Becky 2B-7H-E168	PR
434339	WELL	PR	01/07/2019	OW	123-38110	Woolley Sosa 2E-7H-E168	PR
434340	WELL	PR	01/07/2019	OW	123-38111	Woolley Becky 2A-7H-E168	PR
434341	WELL	PR	01/07/2019	OW	123-38112	Woolley Becky 2E-7H-E168	PR
434342	WELL	PR	07/31/2017	OW	123-38113	Woolley Sosa 2F-7H-E168	PR
434343	WELL	PR	01/07/2019	OW	123-38114	Woolley Becky 2H-7H-E168	PR
436731	WELL	PR	01/07/2019	OW	123-39241	Woolley Becky 2C-7H-E168	PR
436733	WELL	PR	01/07/2019	OW	123-39242	Woolley Becky 2G-7H-E168	PR
436738	WELL	SI	07/01/2020	OW	123-39245	Woolley Sosa 2C-7H-E168	SI
436739	WELL	PR	01/07/2019	OW	123-39246	Woolley Sosa 2G-7H-E168	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Steel rod		
Corrective Action:		Date:	

**Equipment:**

Type		#	corrective date
Bird Protectors		15	
Comment:			
Corrective Action:			Date:
Plunger Lift		15	
Comment:			
Corrective Action:			Date:
Bradenhead		15	
Comment:			
Corrective Action:			Date:
Ancillary equipment		1	

Comment: <a href="#">Electric panel</a>			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	434333	Type:	WELL	API Number:	123-38104	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	434334	Type:	WELL	API Number:	123-38105	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	434335	Type:	WELL	API Number:	123-38106	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	434336	Type:	WELL	API Number:	123-38107	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:									
Corrective Action:					Date:				
Facility ID:	434337	Type:	WELL	API Number:	123-38108	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	434338	Type:	WELL	API Number:	123-38109	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	434339	Type:	WELL	API Number:	123-38110	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	434340	Type:	WELL	API Number:	123-38111	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				

Facility ID: <u>434341</u>	Type: <u>WELL</u>	API Number: <u>123-38112</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>PR</u>	
Corrective Action:	Date:

Facility ID: <u>434342</u>	Type: <u>WELL</u>	API Number: <u>123-38113</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>PR</u>	
Corrective Action:	Date:

Facility ID: <u>434343</u>	Type: <u>WELL</u>	API Number: <u>123-38114</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>PR</u>	
Corrective Action:	Date:

Facility ID: <u>436731</u>	Type: <u>WELL</u>	API Number: <u>123-39241</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>PR</u>	
Corrective Action:	Date:

Facility ID: <u>436733</u>	Type: <u>WELL</u>	API Number: <u>123-39242</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>PR</u>	
Corrective Action:	Date:

Facility ID: <u>436738</u>	Type: <u>WELL</u>	API Number: <u>123-39245</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Idle Well**

Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____	
Comment: _____	
Corrective Action: _____	Date: _____

Facility ID: <u>436739</u>	Type: <u>WELL</u>	API Number: <u>123-39246</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: <u>PR</u>	
Corrective Action:	Date:

**COGCC Comments**

Comment	User	Date
<a href="#">Routine inspection. Location is a tankless system.</a>	silverr	09/23/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503522	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5253755">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5253755</a>