

Inspection Photos
Location Name: Moffat County 24-29
Location ID: 313166



Photo 1. Overview of location taken at entrance.



Photo 2. Annual weeds and erosion on access road.



Inspection Photos
Location Name: Moffat County 24-29
Location ID: 313166



Photo 3. Wellhead. Annual weeds.



Photo 4. Hissing sound coming from this valve on wellhead.

