

Inspection Photos
Location Name: Gruwell Federal 22-32
Location ID: 313323



Photo 1. Overview of location taken at entrance.



Photo 2. Annual weeds on location.



Inspection Photos
Location Name: Gruwell Federal 22-32
Location ID: 313323



Photo 3. Separator does not appear to be in use.



Photo 4. Piece of separator housing becoming debris and migrating off location.

