

Inspection Photos
Location Name: Moffat County 2
Location ID: 312973



**Photo 1. Overview of location taken facing the entrance.
Annual weeds on location.**



Photo 2. Annual weeds on location.



Inspection Photos
Location Name: Moffat County 2
Location ID: 312973



Photo 3. Example of stained soil on location.



Photo 4. Example of stained soil in tank battery and annual weeds on location.

