

Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 1. Overview of location taken from the entrance.



Photo 2. Overview of location taken from northeast corner.



Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 3. Wellhead with vegetation around it.



Photo 4. Valve where hissing sound was heard.

Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 5. Risers not marked for LOTO or abandonment.



Photo 6. Riser not marked for LOT or abandonment.



Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 7. Equipment stored on location.



Photo 8. Equipment stored on location.



Inspection Photos
Location Name: Schroeder 33-32
Location ID: 313167



Photo 9. Equipment stored on location.



Photo 10. Equipment stored on location.