

# Inspection Photos

Operator: Enduring Resources  
API: 067-06984  
Date: 9/23/2020



Photo 1. View of the project area from the southeastern corner facing center.





Photo 2. View of the southern fill slope from the southeastern edge facing westward. Revegetation is progressing with grasses and forbs such as western wheatgrass, crested wheatgrass, wild tarragon, and sand dropseed.





Photo 3. View of Russian knapweeds (approx. 50 individuals) within the southern project area.





Photo 4. View of the reference area comprised of open pinyon and juniper woodland with black sage and grasses/forbs in the understory such as western wheatgrass, Indian ricegrass, and penstemon.





Photos 5/6. View of closed gates after entering (left) after leaving (right)