

Inspection Photos

Location Name: HOWARD USX A-66N64W /9NWSE

Location #: 306349



Photo #1

Howard USX A 9-10 (05-123-24495) Wellsite

Producing | PR

Weeds
prior insp.



Photo #2

Howard USX A 9-10 Wellsite

Producing | PR

Weeds: Mitigated

Inspection Photos

Location Name: HOWARD USX A-66N64W /9NWSE

Location #: 306349



Photo #3

Howard USX A 09-14D, 09-15D, 09-23, 9-10, 9-11

Battery site

Active

Formerly served:

Howard USX A09-09D, A 9-16

Plugged & Abandoned | PA

prior insp.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources