

## Inspection Photos

Location Name: HOWARD USX A-66N64W /9NESW

Location #: 306350



**Photo #1**

**Howard USX A 9-11 (05-123-24496) Wellsite**

**Producing | PR**

*Weeds  
prior insp.*



**Photo #2**

**Howard USX A 9-11 Wellsite**

**Producing | PR**

***Weeds: Mitigated***

## Inspection Photos

Location Name: HOWARD USX A-66N64W /9NESW

Location #: 306350



### Photo #3

Howard USX A 09-14D, 09-15D, 09-23, 9-10, 9-11  
Battery site

**Active**

*Formerly served:*

*Howard USX A09-09D, A 9-16*

*Plugged & Abandoned | PA*

*prior insp.*



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources