

**Inspection Photos**  
**Operator: Enduring Resources**  
**API: 067-07466**  
**Date: 9/23/2020**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern project area facing southward. Revegetation is progressing with grasses and shrubs such as western wheatgrass, rubber rabbitbrush, and sand dropseed.



Photo 2. View of the southern fill slope from the southeastern corner facing westward.



Photo 3. View of the reference area comprised of open pinyon and juniper woodland with black sage and grasses/forbs in the understory such as western wheatgrass, Indian ricegrass, and penstemon.



Photo 3. View of the reference area comprised of pinyon and juniper woodland with understory of shrubs such as gambel oak, antelope bitterbrush, mountain mahogany, and squaw apple, as well as grasses and forbs such as western wheatgrass, squirreltail, and buckwheat.



Photos 4/5. View of closed gates after entering (left) after leaving (right)