

**Inspection Photos**  
**Location Name: Latham 34-2**  
**Location ID: 432800**



**55 Gallon Drum needs secondary containment**