

TEP ROCKY MOUNTAIN LLC
AP-66S95W 15SESE
Location # 335471



**TEP ROCKY MOUNTAIN LLC
AP-66S95W 15SESE
Location # 335471**



Condensate tank capacities are illegible.

**TEP ROCKY MOUNTAIN LLC
AP-66S95W 15SESE
Location # 335471**



Methanol tank label is illegible.



Fence around tank battery is down and damaged around south east corner.

**TEP ROCKY MOUNTAIN LLC
AP-66S95W 15SESE
Location # 335471**



Oil accumulation in pit (414579)

**TEP ROCKY MOUNTAIN LLC
AP-66S95W 15SESE
Location # 335471**



**Gaps in fencing/netting around the pit in
south east corner**

**TEP ROCKY MOUNTAIN LLC
AP-66S95W 15SESE
Location # 335471**



**Gaps in fencing/netting around the pit in
north west corner**