

Inspection Photos
Location Name: KREPS-66N64W /7NWNE
Location #: 323223



Photo #1
Kreps #1 (05-123-12736) Wellsite
Shut-In | SI
Weeds
prior insp.



Photo #2
Kreps #1 Wellsite
Shut-In | SI
Weeds: Mitigated

Inspection Photos
Location Name: KREPS-66N64W /7NWNE
Location #: 323223



Photo #3

Kreps #1 Battery site: Tank

Inactive | Shut-down

prior insp.



Photo #4

Kreps #1 Battery site: Separator, ECD

Inactive | Shut-down

prior insp.