

Inspection Photos

Location Name: HOWARD USX A-66N64W /9SWSW

Location #: 306348



Photo #1

Howard USX A 9-13 (05-123-24494) Wellsite

Shut-In | SI

Weeds

prior insp.



Photo #2

Howard USX A 9-13 Wellsite

Shut-In | SI

Weeds: Remain

prior insp.

Inspection Photos

Location Name: HOWARD USX A-66N64W /9SWSW

Location #: 306348



Photo #3

Howard USX A 9-13 Wellsite

Shut-In | SI

Weeds: Mitigated



Photo #4

Howard USX A 9-13 Battery site

Inactive | Shut-down

prior insp.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources