

# Inspection Photos

9/24/2020

Operator: NONSUCH NATURAL GAS INC -  
10163

Location ID: 453726  
Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 453726



**Photo 1:** Photo taken from the east end of the Location, facing south. Photos 1-3 provide an overview of the production area of the tank battery facility, from south, west to north.



**Photo:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: NONSUCH NATURAL GAS INC - 10163  
Location ID: 453726



**Photo 3:** See comments under photo 1.



**Photo 4:** Photo of meter shed. COGCC Records show meter shed is active and associated with the CSOC 697-14 1 well, API #045-07948.



**Inspection Photos**  
**Operator Name: NONSUCH NATURAL GAS INC - 10163**  
**Location ID: 453726**



**Photo 5:** Photo shows separator equipment on the Location. It is unclear to the COGCC as to what the equipment's current use is on the Location, and if equipment is considered active.



**Photo 6:** Photo shows methanol tank on the Location. It is unclear to the COGCC as to what the equipment's current use is on the Location, and if equipment is considered active.

## Inspection Photos

Operator Name: NONSUCH NATURAL GAS INC - 10163

Location ID: 453726



**Photo 7:** Photo shows 200bbl tank. It is unclear to the COGCC as to what the equipment's current use is on the Location, and if equipment is considered active. Secondary containment remains out of compliance with Rule 906.d.(1). See inspection #696201797 for additional details.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources