

# Inspection Photos

ID: 412295

Operator: RENCO GAS PIPELINE INC

Inspection Date: 9/24/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest. There is an unused compressor engine that appears to be abandoned. This equipment needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

412295 | Date: 9/24/2020

## Inspection Photos



**Photo 2.** There is pipe risers that remain at the location and a steel tank. Does not appear to be in use. Unused equipment needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

412295 | Date: 9/24/2020

## Inspection Photos



**Photo 3.** A steel tank appears to be unused with no secondary containment. There is no vegetation growth around the tank which indicates impacted soil.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

412295 | Date: 9/24/2020