

Inspection Photos

API: 05-061-06590

Operator: OXY USA INC

Inspection Date: 9/24/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020

Inspection Photos



Photo 1. Facing south along the access road. There are signs of erosion along the road. The access road has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020

Inspection Photos



Photo 2. Facing south toward the location. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020

Inspection Photos



Photo 3. Facing southwest along the fill slope which is bare of vegetation and has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020

Inspection Photos



Photo 4. Facing northwest at the location. This area of disturbance is bare of vegetation and needs to be reclaimed. There may be soil issues preventing vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020

Inspection Photos



Photo 5. Facing north toward the location. The location has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020

Inspection Photos



Photo 6. Facing northwest toward the cut slope which has not been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020

Inspection Photos



Photo 7. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020

Inspection Photos



Photo 8. View of groundcover at the location which shows sparse vegetation cover. The main vegetation growing throughout the location was *Senecio douglasii*.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020

Inspection Photos



Photo 9. Facing east toward the surrounding undisturbed area which shows a uniform vegetation cover consisting of Blue grama, Sand dropseed, Prairie threeawn among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06590 | Date: 9/24/2020