

Inspection Photos

Location Name: Anschutz-Williams 5-61-27 SWSW

Location ID: 452726



Photo 1 – Separators



Photo 2 – Tank Battery



Inspection Photos
Location Name: Anschutz-Williams 5-61-27 SWSW
Location ID: 452726



Photo 3 – Tank Battery Sign



Photo 4 – Unused Secondary Containment

Inspection Photos
Location Name: Anschutz-Williams 5-61-27 SWSW
Location ID: 452726




Photo 5 – Unmarked Risers at VRUs




Photo 6 – Stained Soil at LACT