

Inspection Photos

Pit #427371

Operator: SWN

Insp#: 692402535

Insp Date: 9/23/2020






Photo#1:
View over three Pits to East. Insert is entry into Location.

September 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Pit #427371



Photo#2:
View over pit and Scotch thistle established on perimeter.

September 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Pit #427371



Photo#3:
Equipment stored at West end of site.



Photo#4:
View over tank and pits to Northeast.

September 23, 2020



Photo#5:
Close up of Pit interior.

September 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Pit #427371



Photo#6:
COGCC Maps 2017 Aerial showing Four Active Pits.

September 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Pit #427371