

Inspection Photos

API# 081-07775

Operator: GRMR

Insp#: 692402538

Insp Date: 9/23/2020




Photo#1:
View over Location to Southwest.

September 23, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Iles Mountain API# 081-07775



Photo#2:
View of Location to Northeast.

September 23, 2020