

## Inspection Photos

Location Name: H. Huett Consolidation Release

Spill ID: 478005



**Photo 1 –Oily wasted stockpiled on location.**

**Photo 2 – Oily waste stockpiled on location**

**Inspection Photos**  
**Location Name: H. Huett Consolidation Release**  
**Spill ID: 478005**



**Photo 3 – Area of spill excavation**



**Photo 4 – Area of spill excavation**

**Inspection Photos**  
**Location Name: H. Huett Consolidation Release**  
**Spill ID: 478005**



**Photo 5 – Surface soil/vegetation removed from spill area.  
Pooled fluids observed in insp doc#689501090 have been  
removed**