

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2020

Submitted Date:

09/28/2020

Document Number:

689501099**FIELD INSPECTION FORM**Loc ID 475322 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477437	SPILL OR RELEASE	AC	08/04/2020		-	Yoxall Farms Manifold	EI

**General Comment:**

Follow up environmental inspection of Spill ID 477437 (AC)/ Remediation Project No. 15961.

No operator personnel were on site at the time of inspections. Photo attached to document site conditions.

Any corrective actions from previous inspections that have not been addressed are still applicable.



**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: No work has been performed on this spill since the previous inspection. The surface spill area appears to be the same dimensions and has not grown in size. Initial Form 27 (doc # 402486281, Remediation Project No. 15961) has been submitted for the remediation of this spill. The Form 27 lists the date of commencement of site investigation as 10/12/2020 and commencement of Remediation as 10/19/2020. Spill ID 477437 has not been closed and remains active.

Corrective Action: Submit a Supplemental Form 27 requesting closure of Spill ID 477437 with work being performed under Remediation Project No. 15961. Submit a Form 27 Supplemental Report within 45 days of performing the environmental site investigation.

Date: 11/26/2020

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501100	Field Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5257745">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5257745</a>