

Inspection Photos

API: 05-011-06072

Operator: STRACHAN EXPLORATION INC

Inspection Date: 9/24/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-011-06072 | Date: 9/24/2020

Inspection Photos



Photo 1. Facing north toward the location. The crop has not reestablished t the location. There may be potential soil issues affecting crop establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06072 | Date: 9/24/2020

Inspection Photos



Photo 2. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06072 | Date: 9/24/2020

Inspection Photos



Photo 3. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06072 | Date: 9/24/2020

Inspection Photos



Photo 4. Facing south toward the surrounding undisturbed cropland which shows uniform crop cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06072 | Date: 9/24/2020