

Inspection Photos

API: 05-011-06094

Operator: THOMAS L SPRING LLC

Inspection Date: 9/24/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06094 | Date: 9/24/2020

Inspection Photos



Photo 1. Facing west along the access road. The access road has not been reclaimed and there is undesirable weeds along the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06094 | Date: 9/24/2020

Inspection Photos



Photo 2. Facing north along the access road. The access road has not been reclaimed and there is undesirable weeds along the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06094 | Date: 9/24/2020

Inspection Photos



Photo 3. Facing northwest toward the location. There is undesirable weeds (Kochia) throughout the entire location which has grown to 4-6 feet tall.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06094 | Date: 9/24/2020

Inspection Photos



Photo 4. There is equipment that remains at the location that has not been removed. The weeds have grown around the equipment and are a fire hazard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06094 | Date: 9/24/2020

Inspection Photos



Photo 5. Facing southwest at the location. The meter shed and tank battery remains. All equipment should have been removed within 3 months of abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06094 | Date: 9/24/2020

Inspection Photos



Photo 6. Facing toward the tank battery. The weeds are thick and overgrown that the surface of the location was not visible.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06094 | Date: 9/24/2020

Inspection Photos



Photo 7. Facing northeast toward the location. The surrounding field has been mowed however the entire location is completely overgrown with Kochia.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06094 | Date: 9/24/2020

Inspection Photos



Photo 8. Facing west toward the location. The surrounding field has been mowed however the entire location is completely overgrown with Kochia.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-011-06094 | Date: 9/24/2020