

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2020

Submitted Date:

09/29/2020

Document Number:

691201359**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Graber, Candice (Nikki) 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
Oakman, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
472963	SPILL OR RELEASE	CL	08/04/2020		-	Facility #7 Consolidation Line	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill of release area not of nearby wellhead.

Environmental**Spill/Remediation:**

Comment: Inspection of Remediation #15771 progress. The initial clean up and removal of impacted soils has occurred as part of the repair. Inspectors did not find evidence of any additional excavation or soil borings being performed at this site. Extent of impact is unknown at this time. Per Initial Form 27 (Document #402456977) Operator was scheduled to complete remedial Work 10/12/2020.

Corrective Action: In accordance with Rule 906.a Operators shall investigate, clean up, and document impacts resulting from spills/releases as soon as practicable. Supporting documentation is due within 45 days of scheduled commencement. Documentation shall include confirmation soil samples to document removal of impacts from soil in the release area and a site diagram that illustrates the release extent and location of confirmation soil samples.

Date: 11/29/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
691201360	Spill area looking north	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5258972
691201361	Spill area looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5258973